

AIR MONITORING FIELD DATA SHEET
CENTURY MODEL 128 ORGANIC VAPOR ANALYZER
(FLAME IONIZATION DETECTOR)

INCIDENT NAME: BOSSKET SITE

INCIDENT LOCATION: UTICA, NY

DATE AND TIME OF INITIAL ARRIVAL: 6/18/87 1345

WEATHER CONDITIONS: Temperature 84° Pressure ✓
Wind Speed 2-3 MPH Wind Direction SE Humidity ✓
General Weather Conditions SUNNY, CLEAR, WARM

OVA CALIBRATION DATA: EPA ID # Mode
Date Calibrated By Factory

Are there any potential interferences (ie. high winds, electrical wires, chemical interferences, 2-way radios, pressure drop, etc.)
Comments: Results are report as part per million methane

2 WAY RADIOS BEING USED
equivalent. IN LEVEL "B" protection

BACKGROUND LOCATION: TAT OFFICE TRAILER

Time: 1330 Reading: 2ppm Comments:

SAMPLING LOCATION: BOILER ROOM OVER STAIRWELL NEAR MERCURY

Time: 1345 Reading: 2ppm Comments:

SAMPLING LOCATION: Boiler Room - IN STAIRWELL IN MIDDLE OF PIT

Time: ~~1345~~ 1345 Reading: 2 ppm Comments:

SAMPLING LOCATION: IN PIT DIRECTLY ABOVE PILE OF FRESHLY SAVED SOIL

Time: 1345 Reading: 2ppm Comments: ALL READINGS THROUGHOUT
BOILER ROOM WERE EQUAL TO BACKGROUND

SAMPLING LOCATION:

Time: Reading: Comments:

SAMPLING LOCATION:

Time: Reading: Comments:



AIR MONITORING FIELD DATA SHEET
~~HNU (PHOTOIONIZATION DETECTOR)~~
EXPLOSIMETER

INCIDENT NAME: BOSSERT SOX

INCIDENT LOCATION: UTICA, NEW YORK

DATE AND TIME OF INITIAL ARRIVAL: 6/18/87 1345

WEATHER CONDITIONS: Temperature 84° Pressure _____
Wind Speed 2-3 MPH Wind Direction ESE Humidity MED
General Weather Conditions SUNNY, WARM

~~EXPLOSIMETER~~ CALIBRATION DATA: EPA ID # _____ Probe EPA ID # _____
Probe _____ (eV) Date calibrated _____ Person _____
Unit Charged _____ Span Setting _____ Lense Cleaned _____
Calibration Information _____

Are there any potential interferences (ie. high winds, electrical wires, large temperature variation, pressure drop, high humidity chemical interferences, 2- way radios, etc.)

Comments: Results are recorded in part per million benzene equivalent - IN LEVEL "B" PROTECTION

BACKGROUND LOCATION: DESID TAT OFFICE TRAILER

Time: 1330 Reading: 217.02 Comments: _____
0% LEL

SAMPLING LOCATION: IN BULLER ROOM ABOVE STAIRWELL

Time: 1345 Reading: 217.02 Comments: _____
0% LEL

SAMPLING LOCATION: BULLER ROOM, IN PIT AT BOTTOM OF STAIRWELL

Time: 1345 Reading: 217.02 Comments: _____
0% LEL

SAMPLING LOCATION: IN PIT AS DIRECTLY ABOVE FRESHLY SCRAPED SOIL

Time: 1345 Reading: 217.02 Comments: ALL READINGS IN BULLER ROOM
0% LEL EQUAL TO BACKGROUND.

SAMPLING LOCATION: _____

Time: _____ Reading: _____ Comments: _____

AIR MONITORING FIELD DATA SHEET
CENTURY MODEL 128 ORGANIC VAPOR ANALYZER
(FLAME IONIZATION DETECTOR)

INCIDENT NAME: BOSSERT MFG.

INCIDENT LOCATION: 1002 OSWEGO ST.

UTICA NEW YORK

DATE AND TIME OF INITIAL ARRIVAL: 06/18/87 1355

WEATHER CONDITIONS: Temperature 91°F Pressure _____
Wind Speed _____ Wind Direction _____ Humidity _____
General Weather Conditions CLEAR/SUNNY/HOT

OVA CALIBRATION DATA: EPA ID # _____ Mode _____
Date Calibrated By Factory 5/20/87

Are there any potential interferences (ie. high winds, electrical wires, chemical interferences, 2-way radios, pressure drop, etc.)
Comments: Results are report as part per million methane

equivalent. 2WAY RADIOS - EQUIPMENT

BACKGROUND LOCATION: DECON SHED

Time: 1355 Reading: 2.0 Comments: _____

SAMPLING LOCATION: AREAS #19, 18, 4, 12, 16, 14

Time: 1355-1420 Reading: 2.0 Comments: _____

SAMPLING LOCATION: AREA #13 1ST FLOOR

Time: 1420 Reading: 3.0-4.0 Comments: BOBCAT RUNNING INTERMITTENTLY

SAMPLING LOCATION: AREA #13 2ND FLOOR

Time: 1425 Reading: 18.0 Comments: "LIQUID NAIL" BEING USED TO COVER WINDOWS WITH VISQUEEN

SAMPLING LOCATION: AREA #10/#11 2ND FLOOR

Time: 1430 Reading: 2.0 Comments: _____

SAMPLING LOCATION: _____

Time: _____ Reading: _____ Comments: _____